Date: Monday, 9/10/2007 1:18:54 PM	175
Viser: Kim Johnston Proce	ess Sheet Split 2
Customer : CU-DAR001 Dart Helicopters Services Job Number : 34474 Estimate Number : 12578 P.O. Number : MA This Issue : 9/10/2007 S.O. No. : MA Prsht Rev. : NC First Issue : MC Previous Run : 33844 Written By : SMALL /MED FAB Checked & Approved By : Checked & Approved By : Est Rev: A New Issue 07.05.24 EC Additional Product	Part Number : D3560041 Drawing Number : D3560 UNDER REVIEW Project Number : N/A Drawing Revision : B/C Material : N/A Due Date : 9/17/2007 Qty: 12 Um: Each
Job Number:	
Seq. #: Machine Or Operation:	Description :
1.0 M6061T6B0500X05000 6061-T6	Bar 50* x 5.0*
Comment: Qty.: 1.4648 f(s)/Unit Total: 17.5770 f(s) 6061-T6 Bar 0.50" x 5.00" Batch: M10 5 6 4 6	Ind 07/09/20 (2)
2.0 BAND SAW BAND SA	AW IIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII
Cut blanks 16.750" long	and 07/09/20 (12)
3.0 HAAS1 HAAS CI	NC VERTICAL MACHINING #1
Comment: HAAS CNC VERTICAL MACHINING #1 1- Mill as per Folio FA693 Rev: AA & Dwg D356	60 Rev: C
2-C'sink 0.196" hole on manual mill as per dwg D35	560
	J.L 07/09/2
	T PARTS AS THEY COME OFF MACHINE
Comment: INSPECT PARTS AS THEY COME OFF MACHINE	CHECK 04104/21
Comment: SECOND CHECK	F 07-04.21 (12)

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE By Date Qty Chief Prod		Approval Chief Eng / Prod Mgr	Approval QC Inspector		
17w2/17							
Dort No.			55 25X				COST PARTS

Part No:	PAR #:	Fault Category:	NCR: Yes No DQA:	Date:	
			QA: N/C Closed:	Date:	14

NCR:		W	ORK OR	DER NON-CONFORMANCE	(NCR)			
DATE	CTED	Description of NC	1	Corrective Action Section B		Verification	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector
		- I arm scrapped, moved while roughing outside profile - bolts were not tight enough		- scrap + replace	ゴル	(//	
اطعماء	3	roughing outside profile	1	,,	1)	Cn	1/	6
041011-1			051012		07/09/21	Shortal	l'asiouz.	Model
		Human eron				- oug		Moy
			d.				1,520	
i i i				7			j.	
				#				
100								
							-	48

NOTE: Date & initial all entries

Date: * Monday, 9/10/2007 1:18:54 PM User: . Kim Johnston **Process Sheet** Drawing Name: ARM Customer: CU-DAR001 Dart Helicopters Services Job Number: 34474 Part Number: D3560041 Job Number: Seq. #: Description: Machine Or Operation: D35921 PLATE 6.0 12.0000 Each(s) Comment: Qty.: Each(s)/Unit Total: 7.0 Comment: LARGE FABRICATION RESOURCE 1 1-Weld assembly as per dwg D3560 INSPECT WORK TO CURRENT STEP 8.0 QC5 Comment: INSPECT WORK TO CURRENT STEP VISUAL WELDING INSPECTION 9.0 Comment: VISUAL WELDING INSPECTION 10.0 HAND FINISHING RESOURCE #1 Comment: HAND FINISHING RESOURCE #1 Chemical Conversion Coat as per QSI 005 4.1 POWDER COATING POWDER COAFING 11.0 Comment: POWDER COATING Powder Coat White Gloss (Ref: 4.3.5.1) as per QSI 005 4.3 12.0 Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION PACKAGING RESOURCE Comment: PACKAGING RESOURCE #1 Identify and Stock Location:

Form mrocess

Page 2

Dart /	Aeros	pace	Ltd
The state of the s		and the facilities of the second seco	-

W/O:	77	WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
04-10-25	1	1. well assembly as per deg.) 3560 part should be pre heated to 60-70 calcius (before welding own to bracket.	M	gr. 10:25		Corroas.	1000
				34	-		

Part No:	PAR #:	Fault Category:	NCR: Yes No DQA:	Date:
			QA: N/C Closed:	Date:

NCR:	事件。 新有1 。		WORK ORDI	VORK ORDER NON-CONFORMANCE (NCR)				
		Description of NC		Corrective Action Section B		Verification	Ammanual	
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspector
						-		
y"anada								-7/5
Prof.							7.4	#
							_	8-1
								2
						1	ľ	

NOTE: Date & initial all entries

Date:

Monday, 9/10/2007 1:18:54 PM

User:

Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: ARM

Part Number: D3560041

Job Number: 34474

Seq. #:

Job Number:

Machine Or Operation:

Description:

14.0

QC21

FINAL INSPECTION/W/O RELEASE





Comment: FINAL INSPECTION/W/O RELEASE

Job Completion



4 2.60 16

-							
1 7	21	-	Δ.		00	pace	 6 M
_	aı	100		CI	US	$\mu a \nu i$	w

W/O:			WC	RK ORDER CHANGE	S					
DATE	STEP	PRO	PROCEDURE CHANGE				Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
	And the second						;ª		×	
										1
Part No:		PAR #:	Fault Cateç	Jory:						14
								<u> </u>	_ Date: _	
NCR:		Maria de la Company	VORK ORDE	R NON-CONFORMA	NCE	(NCR)				
DATE	OTED	Description of NC		Corrective Action Section			Verific	ation	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Section		Chief Eng	QC Inspector
			,							
	1.0 Table 10									

NOTE: Date & initial all entries

DART AEROSPACE LTD	Work Order:	34474
Description: Arm	Part Number:	D3560-1
Inspection Dwg: D3560 Rev: 8		Page 1 of 1


FIRST ARTICLE INSPECTION CHECKLIST

X First Article	Prototype
-----------------	-----------

Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
Ø0.507	+0.000/-0.001	.5065				
Ø0.196	+0.005/-0.001	.196	1			
Ø1.000	+0.010/-0.001	1.004				
0.500	+/-0.010	495	1			
0.250	+/-0.010	.251				
0.275	+/-0.010	275	1			
0.188	+/-0.010	185	/			
2.000	+/-0.010	2000			Lie Lie	
1.700	+/-0.010	1.700			<u> </u>	
Ø0.385 x 100°	+/-0.010 x 0.5°	-380×100				
0.250 Deep	+/-0.010	254				
				5)		
(1)						4-77
			`			
			4			

Measured by:	ゴル	Audited by:	36	Prototype Approval:	N/A
Date:	07/09/20	Date:	07-09.70	Date:	N/A


Rev	Date	Change	Revised by	Approved
А	07.01.17	New Issue P/O D3560-041	KJ/JLM LA	
В	07.06.13	Dimensions updated per Dwg Rev B	KJ/JLM	E




D3550-1 ARM (-041, SHOWN)
OR D3560-2 ARM (-042, OPPOSITE)

D3592-1 PLATE,
SEE DETAIL A

D3560-041 ARM WELDMENT (SHOWN), D3560-042 ARM WELDMENT (OPPOSITE)



D3560-043 ARM WELDMENT (SHOWN), D3560-044 ARM WELDMENT (OPPOSITE)



(SCALE 1:1)

GENERAL NOTES

- 1) WELD PER QSI 004
- 2) FINISH: CHEMICAL CONVERSION COAT PER DART QSI 005 4.1
- 3) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
- 4) ALL DIMENSIONS ARE IN INCHES



	С		07.06.19	REMOVE POWD	DER COAT	
	В		07.01.15	REDESIGN AS	WELDMENT, ADD POCKETS	
	A		06.09.25	NEW ISSUE		
COPYRIGHT @ 2006 BY DART AEROSPACE LTD.	DESIGN		DRAWN BY	DART	DART AEROSPACE LTD.	
THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE	CHECKED		APPROVED #	DRAWING NO. D3560	REV. C SHEET 1 OF 3	
OR COPIED OR COMMUNICATED TO ANY DTHER PERSON WITHOUT WRITTEN PERWISSION FROM DART AEROSPACE LTD.	DATE 07.06.19			ARM WELDMENT	SCALE 1:4	



